



Posted on Sat, Apr. 12, 2008

Regulators told of possible wiring problems on jetliners took their time ordering repairs

By BOB COX
McClatchy Newspapers

FORT WORTH, Texas | Airline safety regulators knew for years that MD-80 airliners might have a wiring problem like the one that led last week to the grounding of American Airlines planes.

But a review of Federal Aviation Administration documents indicates that the agency was in no hurry to force airlines to make fixes.

The FAA had begun the process by June 2003 to issue an airworthiness directive ordering inspections and repairs of MD-80 wiring bundles, located near the plane's main landing gear, and may have started as early as 2001, according to agency documents.

The directive didn't take effect until September 2006, when airlines were given 18 months to comply.

Years earlier, before McDonnell Douglas, the manufacturer of the MD-80, merged with Boeing, it had issued service bulletins warning airlines of the potential problem. FAA documents refer to a November 2002 Boeing service-alert bulletin that "supersedes and cancels" earlier McDonnell Douglas service bulletins.

Despite the warnings, airlines have filed few reports of serious problems with the wiring over the years.

A review by the *Fort Worth Star-Telegram* of more than 24,000 MD-80 maintenance and incident reports filed by airlines with the FAA since 2000 shows only one case of chafed and burned wires in the wiring bundle in question. That occurred in August 2005 on a Delta Air Lines MD-88 while it taxied to the gate.

John Eakin, owner of Air Data Research in Helotes, Texas, did his own search of FAA records dating to the 1980s. He said he found nothing in the data that suggests there was a problem that required drastic action by the FAA, such as the grounding of a fleet.

Even if there were discrepancies between the exact repair methods required by the FAA and the way they were performed by an airline such as American, Eakin said, they probably could have been fixed during regular maintenance without posing any danger.

"If I thought the airlines had screwed up, I'd be the first to criticize them," he said. "But in this case, I think it's an overreaction by the FAA."

Over the lifetime of an aircraft model, which can be 30 or more years, manufacturers notify airlines, repair centers and the FAA when a problem is discovered that needs corrective action. That notification takes the form of a service bulletin.

A more urgent notice is a service-alert bulletin. Lawyers say those bulletins, even without formal FAA action, carry something akin to the force of law.

"You've got to get that done," said New York aviation lawyer Brian Alexander, a former military pilot. "To ignore that is breach of the standard of care" expected of an airline or other aircraft operator.

After a service bulletin is issued, the FAA typically goes through the process of issuing a formal, legal airworthiness directive ordering airlines to take action.

Lynn Tierney, the FAA's assistant administrator for communications, said it was American's decision to ground its

planes until they could be brought into compliance with the FAA's exact safety requirements. The airline could have avoided doing so, Tierney said, by doing the modifications in the "18 months they were given to do the work."

That's not exactly how American officials see it.

In a conference with employees Thursday, Bob Reding, American's executive vice president of operations, said the airline worked with Boeing and the FAA in 2004 to design a way to address the problem with chafing and worn wires.

Boeing issued an updated service bulletin based on that work.

The FAA issued its order in September 2006 with the specific requirements contained in the Boeing service bulletin and gave airlines 18 months to comply.

American, however, was already implementing the maintenance work called for in the service bulletin on its entire MD-80 fleet and had completed the work before the March 5 deadline, airline spokesman John Hotard said.

Then in late March, after the FAA announced that it was taking action against Southwest Airlines for missing required inspections, the agency began audits of all airline inspection and maintenance records. When FAA inspectors looked at several American MD-80s, they found what Reding called minor differences between the way American had performed the work and the specific details of the airworthiness directive.

According to Hotard, there were minor differences between the way American interpreted the Boeing service bulletin and the exact FAA requirements, which in the past had never been a problem. American set out to correct those changes. Then Monday, a new FAA inspection called for some other changes including the replacement of parts American had used that were not approved by the FAA.

American officials then made the decision to ground the planes, fully expecting that the FAA would require them to do so anyway.

Planes back in the air

DALLAS | American Airlines on Saturday received clearance from federal officials to return all but three of its grounded jets to service.

American was back to normal operations at Kansas City International Airport by 10:30 a.m. Saturday. Two flights were canceled early in the day.

Last week American canceled about 3,000 flights, including dozens at KCI.

| *Staff and wire reports*

© 2007 Kansas City Star and wire service sources. All Rights Reserved. <http://www.kansascity.com>